




acoustic microscopy

SAM evaluation of wire and cable



The SAM image is showing a broken wire encapsulated in a composite material. The white areas are air inclusions.



broken wire